

**LANCASHIRE TESTING SERVICES LIMITED**

Lyon Road Industrial Estate : Kearsley : Bolton

Lancashire : BL4 8NB

Tel: +44 (0) 1204 792858

Email: enquiries@ltslab.co.uk

[www.ltslab.co.uk](http://www.ltslab.co.uk)

9630

# TEST CERTIFICATE

<b>CLIENT:</b>	Agua Fabrics Ltd Hyde House The Hyde London NW9 6LH -	<b>Certificate Number:</b>	<b>UK1800424 -6</b>
		<b>Date Received:</b>	25/06/2018
		<b>Date Issued:</b>	29/06/2018
		<b>Issue Number:</b>	1
<b>Contact:</b>	Suzanne Ralton	Changes from previous issue (if applicable)	
<b>Tel:</b>	020820500050	_____	
<b>Email:</b>	suzanne@aguafabrics.com		

**SAMPLE IDENTIFICATION**

Sample Name / Reference:            Libra  
Order / Batch No:                    -  
Customer:                                Agua Fabrics  
Fabric Composition:                  100% Polyester  
Colour:                                  -  
Quality:                                  -  
Width:                                    -

**SPECIFICATION**

BS7176:2007 + A1:2011 - Medium Hazard

**TEST METHOD**

Flammability:                        BS EN 1021-1:2006 Part 1: Ignition source smouldering cigarette  
  BS EN 1021-2:2006 Part 2: Ignition source match flame equivalent  
  BS 5852:2006 Crib Ignition source 5  
Pre-treatment:                        BS 5852:2006 Annex E - Water soaking procedure

**Conclusion**

The composite tested:           **Complies**                                with the flammability requirements of:  
BS 7176:2007 + A1:2011 Medium hazard, taking into account uncertainty of measurement.

Please note that copies of this original certificate are not valid



**LANCASHIRE TESTING SERVICES LIMITED**

Lyon Road Industrial Estate : Kearsley : Bolton  
 Lancashire : BL4 8NB  
 Tel: +44 (0) 1204 792858  
 Email: enquiries@ltslab.co.uk  
 www.ltslab.co.uk



9630

**TEST CERTIFICATE**

<b>Test Results:-</b>						
<b>BS7176:2007 + A1:2001 - Medium Hazard - Specification for resistance to ignition of upholstered furniture for non-domestic seating by testing composites</b>						
<i>"The following test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use."</i>						
Sample Code	UK1800424 -6					
Sample / Name Reference	Libra					
Client	Agua Fabrics Ltd					
Date of test	29/06/2018					
Pre-Treatment	BS 5852:2006 Annex E - Water soaking procedure Line Dried during at ambient temperature					
Filling Type	Carpenter/RX36110 CMHR polyurethane foam of approximate density 36Kg/m3					
Size of test rig	Small: Back - 450 x 300 ± 2mm + Seat - 450 x 150 ± 2mm					
Test Conditions	Period h	Temperature °C	Relative humidity %	Air Flow m/s	Volume m <sup>3</sup>	
Conditioning of test specimens	≥16	23±2	50±5	-	-	
Testing conditions	-	10-30	15-80	0.02-0.2	>20	
Testing Source	BS EN 1021-1:2006 Smouldering Cigarette Source					
Testing time limit	60 minutes after placement of smouldering cigarette.					
Test No.	Position	Ignition/N on Ignition	Duration of: (min.sec)			Smouldering and flaming criteria exceeded: (If any)
			Ignition Source	Flames	Smoke	
1	RHS	NI	24.28	-	27.39	-
2	M	NI	25.28	-	28.11	-
3	-	-	-	-	-	-
Testing Source	BS EN 1021-2:2006 Match flame ignition source					
Testing time limit	2 minutes after removal of burner tube (120 seconds)					
Test No.	Position	Ignition/N on Ignition	Duration of: (sec)			Smouldering and flaming criteria exceeded: (If any)
			Ignition Source	Flames	Smoke	
1	RHS	NI	15	16	29	-
2	M	NI	15	15	33	-
3	LHS	NI	15	15	35	-
<b>RESULT: SMOULDERING CIGARETTE SOURCE</b>					<b>PASS</b>	
<b>MATCH FLAME IGNITION SOURCE</b>					<b>PASS</b>	
KEY: I = Ignition, NI = Non Ignition, LHS = Left hand side, M = Middle, RHS = Right hand side						

Please note that copies of this original certificate are not valid

**Issue Number: 1**

This report relates only to the sample tested and does not guarantee the bulk of the material to be of equal quality

**LANCASHIRE TESTING SERVICES LIMITED**

Lyon Road Industrial Estate : Kearsley : Bolton

Lancashire : BL4 8NB

Tel: +44 (0) 1204 792858

Email: enquiries@ltslab.co.uk

[www.ltslab.co.uk](http://www.ltslab.co.uk)

9630

# TEST CERTIFICATE


**Test Results:-****BS7176:2007 + A1:2001 - Medium Hazard - Specification for resistance to ignition of upholstered furniture for non-domestic seating by testing composites***"The following test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use."*


Sample Code	UK1800424 -6									
Sample Reference	Libra									
Client	Agua Fabrics Ltd									
Date of test	29/06/2018									
Pre-Treatment	BS 5852:2006 Annex E - Water soaking procedure Line Dried during day at ambient temperature									
Filling Type	Carpenter/RX36110 CMHR polyurethane foam of approximate density 36Kg/m3									
Size of test rig	Large: Back - 450 x 450 ± 2mm + Seat - 450 x 300 ± 2mm									
Test Conditions	Period h	Temperature °C	Relative humidity %	Air Flow m/s	Volume m <sup>3</sup>					
Conditioning of test specimens	≥16	23±2	50±5	-	-					
Testing conditions	-	10-30	15-80	0.02-0.2	>20					
Testing Source	BS 5852:2006 Crib Ignition source 5									
Testing time limit	10 minutes after ignition of crib. Observed for 60 minutes in total.									
Test No.	Position	Ignition/N on Ignition	Duration of: (min.sec)		Extent of Damage to component: mm					
			Flames	Smoke	Horizontal			Vertical		
					Width	Length	Depth	Width	Depth	
1	M	NI	3.49	8.12	170	131	73	155	73	
2	M	NI	4.05	9.14	170	132	61	161	69	
<b>RESULT:</b>		<b>CRIB IGNITION SOURCE 5</b>						<b>PASS</b>		

KEY: I = Ignition, NI = Non Ignition, LHS = Left hand side, M = Middle, RHS = Right hand side

Test No.	Time for: (sec)		
	Ignition of test pieces	Cover Splitting	Extinction
1	-	-	-
2	-	-	-

On behalf of Lancashire Testing Services :

Tony Alcock,  
Laboratory Technician:
  
 John Marsh,  
Laboratory Technician:

  
 Peter Collings,  
Operations Manager:

Please note that copies of this original certificate are not valid

**Issue Number: 1**

This report relates only to the sample tested and does not guarantee the bulk of the material to be of equal quality